



## DIR-3040 Firmware Release Notes

**Firmware:** 1.13B03 Hotfix

**Hardware:** Todas as versões Ax

**Data:** 08/06/2021

### Correções:

- CVE-2021-21816 - Syslog information disclosure vulnerability
- CVE-2021-21817 - Zebra IP Routing Manager information disclosure vulnerability
- CVE-2021-21818 - Zebra IP Routing Manager hard-coded password vulnerability
- CVE-2021-21819 - Libcli command injection vulnerability
- CVE-2021-21820 - Libcli Test Environment hard-coded password vulnerability

### Relatório de terceiros:

Múltiplas vulnerabilidades reportadas por CISCO TALOS com os CVE IDs listados acima.

---

**Aviso Legal:** Observe que este é um software beta, firmware beta ou versão de correção que ainda está em teste final antes de seu lançamento oficial. O software beta, firmware beta ou versão de correção (hotfix) é fornecido “como está” e “conforme disponível” e o usuário assume todos os riscos e responsabilidades pelo uso. A D-Link não oferece nenhuma garantia, expressa ou implícita, quanto à adequação ou usabilidade do software ou firmware beta. A D-Link não será responsável por qualquer perda, seja essa perda direta, indireta, especial ou consequential, sofrida por qualquer parte como resultado do uso do software ou firmware beta.